



**FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION**
CENTRAL DISTRICT
3319 MAGUIRE BOULEVARD, SUITE 232
ORLANDO, FLORIDA 32803-3767

RICK SCOTT
GOVERNOR

JENNIFER CARROLL
LT. GOVERNOR

HERSCHEL T. VINYARD JR.
SECRETARY

November 15, 2012

E-MAIL

sgrant@wm.com

Ms. Sheree Grant
Vista Landfill
242 W. Keene Road
Apopka, FL 32703

OCD-SW-12-447

Orange County – SW WACS # 87081
Vista Class III Landfill
Inspection Report – Cell 3 Construction

Dear Ms. Grant:

On September 24 and 27, 2012 a representative of the Florida Department of Environmental Protection conducted an inspection of the Cell 3 construction at the above referenced facility to determine the status of compliance with the Department's solid waste regulations. At the time of this inspection, the construction activities were being conducted in compliance with applicable Rules and permits. A copy of the inspection report is attached for your review.

Please contact me by telephone at (407) 897-4314 or by e-mail at kim.rush@dep.state.fl.us if you have any questions or need additional information.

Sincerely,

A handwritten signature in black ink that reads 'Kimberly Rush'.

Kimberly Rush, P.E.
Solid Waste Permitting

Attachment: Inspection Report



Florida Department of
Environmental Protection
Inspection Checklist

FACILITY INFORMATION:

Facility Name: VISTA LANDFILL, LLC., CLASS III (BUTTREY/KEENE RD SOUTH)

On-Site Inspection Start Date: 09/24/2012

On-Site Inspection End Date: 09/24/2012

WACS No.: 87081

Facility Street Address: 230 WEST KEENE RD

City: APOPKA

County Name: ORANGE

Zip: 32703

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Kimberly M. Rush, Inspector

Other Participants: Sheree Grant, Representative; Tommy Bradford, Representative; Yves Carrion, Representative

INSPECTION TYPE:

Construction Completion Certification Inspection for Landfill - Class III facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

COMMENTS:

09/26/2012

Cell 3 Construction 9/24/12:

Cell 3 liner installation activities were observed. Approximately 3/4 of the geomembrane was installed at the time of this inspection on 9/24/12. The sump area was being prepped for installation. CQA activities were being performed.

Wet Area:

Prior to liner installation, a wet spot in the North East corner of cell 3 was noticed. 6-12 inches of the subgrade was removed and the soil underneath was dry. The corrective actions were detailed in an email dated 9/19/12 from Waste Management, Paul Bermillo.

Cell 3 Construction 9/27/12:

Cell 3 geocomposite installation was observed on 9/27/12. CQA activities were being performed on the geocomposite materials and installation.

ATTACHMENTS:

Inspection Date: 09/24/2012

Geomembrane Installation



Geomembrane CQA



GCL Layer



Connecting Geonet



Sewing of Geocomposite



Inspection Date: 09/24/2012

Signed:

Kimberly M. Rush

PRINCIPAL INSPECTOR NAME

Inspector

PRINCIPAL INSPECTOR TITLE**PRINCIPAL INSPECTOR SIGNATURE**

FDEP

ORGANIZATION

9/26/2012

DATE

Sheree Grant

REPRESENTATIVE NAME

Representative

REPRESENTATIVE TITLE

NO SIGNATURE

REPRESENTATIVE SIGNATURE

Vista

ORGANIZATION

Tommy Bradford

REPRESENTATIVE NAME

Representative

REPRESENTATIVE TITLE

NO SIGNATURE

REPRESENTATIVE SIGNATURE

CDM Smith

ORGANIZATION

Yves Carrion

REPRESENTATIVE NAME

Representative

REPRESENTATIVE TITLE

NO SIGNATURE

REPRESENTATIVE SIGNATURE

CDM Smtih

ORGANIZATION

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.