



**FLORIDA DEPARTMENT OF
ENVIRONMENTAL PROTECTION**

CENTRAL DISTRICT
3319 MAGUIRE BOULEVARD, SUITE 232
ORLANDO, FLORIDA 32803-3767

RICK SCOTT
GOVERNOR

CARLOS LOPEZ-CANTERA
LT. GOVERNOR

JONATHAN P. STEVERSON
SECRETARY

March 13, 2015

Jackey Jackson
Sumter County Solid Waste Facility
7375 Powell Road
Wildwood, FL 34785
Jackey.Jackson@sumtercountyfl.gov

Re: Sumter County TS/Landfill LTC
SW WACS #53008
Sumter County
SPCD-CAP-15-3226

Dear Mr. Jackson:

Department personnel conducted an inspection of the above-referenced facility on March 9, 2015. Based on the information provided during and following the inspection, the facility was determined to be in compliance with the Department's rules and regulations. A copy of the inspection report is attached for your records.

The Department appreciates your efforts to maintain this facility in compliance with state and federal rules. Should you have any questions or comments, please contact Katelyn Wright at 407-897-2923 or via e-mail at Katelyn.J.Wright@dep.state.fl.us.

Sincerely,

A handwritten signature in cursive script that reads "Wanda Parker-Garvin".

Wanda Parker-Garvin, Environmental Manager
Central District
Florida Department of Environmental Protection

WPG/kw

Enclosures: Inspection Report



Florida Department of
Environmental Protection
Inspection Checklist

FACILITY INFORMATION:

Facility Name: SUMTER COUNTY TS / LANDFILL LTC

On-Site Inspection Start Date: 03/09/2015

On-Site Inspection End Date: 03/09/2015

WACS No.: 53008

Facility Street Address: 835 CR 529

City: SUMTERVILLE

County Name: SUMTER

Zip: 33585

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Katelyn J Wright, Inspector

Other Participants: Brad Whidden, Inspector; Jackey Jackson, Representative

INSPECTION TYPE:

Routine Operation Inspection for WPF - Waste Tire Processing Facility

Routine Operation Inspection for WPF - Source-Separated Organics Proc Fac (SOPF) facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

COMMENTS:

03/10/2015

The waste tire processing facility appeared to be maintained according to permit conditions and applicable rules. All tires on-site are stored in a roll-off container off the ground. At the time of the inspection, the most recent fire safety survey was not available. On 3/10/15 Jackey Jackson emailed a copy of the fire safety survey dated 4/24/14.

All yard trash kept on-site is also stored in a roll-off container off the ground, and the facility appeared to be in compliance with permit conditions and applicable rules.

The citizen drop off area was observed during the inspection and containers of used oil were properly labeled and maintained.

ATTACHMENTS:

Inspection Date: 03/09/2015

Yard trash contained in roll-off



Citizen drop-off area



Inspection Date: 03/09/2015

Signed:

Katelyn J Wright

PRINCIPAL INSPECTOR NAME**PRINCIPAL INSPECTOR SIGNATURE**

Inspector

PRINCIPAL INSPECTOR TITLE

FDEP

ORGANIZATION

3/11/2015

DATE

Brad Whidden

INSPECTOR NAME

Inspector

INSPECTOR TITLE

NO SIGNATURE

INSPECTOR SIGNATURE

FDEP

ORGANIZATION

Jackey Jackson

REPRESENTATIVE NAME

Representative

REPRESENTATIVE TITLE

NO SIGNATURE

REPRESENTATIVE SIGNATURE

Sumter County

ORGANIZATION**Supervisor:** Wanda Y. Parker-Garvin *WP-G*

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.