



Florida Department of Environmental Protection

Central District
3319 Maguire Boulevard, Suite 232
Orlando, Florida 32803-3767

Rick Scott
Governor

Carlos Lopez-Cantera
Lt. Governor

Jonathan P. Steverson
Secretary

August 2, 2016

Jackey Jackson, Assistant Public Works Director
Sumter County Solid Waste
835 County Road 529
Lake Panasoffkee, FL 33538
Jackey.Jackson@sumtercountyfl.gov

Re: Sumter County TS/Landfill LTC
SW Facility ID #53008
Sumter County

Dear Mr. Jackson:

Department personnel conducted an inspection of the above-referenced facility on July 20, 2016. Based on the information provided during and following the inspection, the facility was determined to be in compliance with the Department's rules and regulations. A copy of the inspection report is attached for your records.

The Department appreciates your efforts to maintain this facility in compliance with state and federal rules. Should you have any questions or comments, please contact Manuel F. Cardona at 407-897-4134 or via e-mail at Manuel.Cardona@dep.state.fl.us.

Sincerely,

A handwritten signature in black ink, appearing to read "Reggie Phillips".

Reggie Phillips, Manager
Central District
Florida Department of Environmental Protection

Enclosure: Inspection Report



**Florida Department of
Environmental Protection
Inspection Checklist**

FACILITY INFORMATION:

Facility Name: SUMTER COUNTY TS / LANDFILL LTC

On-Site Inspection Start Date: 07/20/2016

On-Site Inspection End Date: 07/20/2016

WACS No.: 53008

Facility Street Address: 835 CR 529

City: SUMTERVILLE

County Name: SUMTER

Zip: 33585

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Manuel F. Cardona, Inspector

Other Participants: Katelyn J. Wright, Inspector; Nick McCollum, Representative

INSPECTION TYPE:

Routine Operation Inspection for WPF - Waste Tire Processing Facility

ATTACHMENTS TO THE INSPECTION CHECK LIST:

This Cover Page to the Inspection Checklist may include any or all of the following attachments as appropriate.

COMMENTS:

The waste tire processing facility appeared to be maintained in accordance with permit conditions and applicable rules. Tires are stored in a roll-off containers.

Inspection Date: 07/20/2016

ATTACHMENTS:

Rim Removal Equipment

Waste Tire Roll-Off #1



Waste Tire Roll-Off #2



Inspection Date: 07/20/2016

Signed:

Manuel F. Cardona
PRINCIPAL INSPECTOR NAME

Inspector
PRINCIPAL INSPECTOR TITLE


PRINCIPAL INSPECTOR SIGNATURE

FDEP
ORGANIZATION 07/20/2016
DATE

Katelyn J. Wright
INSPECTOR NAME

Inspector
INSPECTOR TITLE

NO SIGNATURE REQUIRED
INSPECTOR SIGNATURE

FDEP
ORGANIZATION

Nick McCollum
REPRESENTATIVE NAME

Representative
REPRESENTATIVE TITLE

NO SIGNATURE REQUIRED
REPRESENTATIVE SIGNATURE

Sumter County Solid Waste
ORGANIZATION

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.

Report Approvers:

Approver: Reginald F. Phillips

Inspection Approval Date: 08/01/2016