



**Florida Department of
Environmental Protection
Inspection Checklist**

FACILITY INFORMATION:

Facility Name: PASCO COUNTY RESOURCE RECOVERY

On-Site Inspection Start Date: 01/19/2018

On-Site Inspection End Date: 01/19/2018

WACS No.: 45799

Facility Street Address: 14230 HAYS RD

City: SPRING HILL

County Name: PASCO

Zip: 34610

INSPECTION PARTICIPANTS:

(Include ALL Landfill and Department Personnel with Corresponding Titles)

Principal Inspector: Benjamin Hsu, Inspector

Other Participants: Mike Frestick, Representative

INSPECTION TYPE:

Routine Closure Inspection for WPF - Disaster Debris Management Site (DDMS)

COMMENTS:

The facility was inspected for DDMS closure on 1/19/18 9:30AM.

The facility had one remaining pile of mulch for beneficial use, but otherwise was clear of yard trash debris. No evidence of environmental damage was noted during the inspection.

A WACS closure confirmation email was sent to the facility on 1/23/18.

ATTACHMENTS:

Satellite Overview Of Location



DDMS Photo #1



Inspection Date: 01/19/2018

DDMS Photo #2



DDMS Photo #3



Inspection Date: 01/19/2018

Signed:

Benjamin Hsu
PRINCIPAL INSPECTOR NAME

Inspector
PRINCIPAL INSPECTOR TITLE

Benjamin Hsu
PRINCIPAL INSPECTOR SIGNATURE

FDEP
ORGANIZATION 01/19/2018
DATE

Mike Frestick
REPRESENTATIVE NAME

Representative
REPRESENTATIVE TITLE

NO SIGNATURE REQUIRED
REPRESENTATIVE SIGNATURE

Pasco County
ORGANIZATION

NOTE: By signing this document, the Site Representative only acknowledges receipt of this Inspection Report and is not admitting to the accuracy of any of the items identified by the Department as "Not Ok" or areas of concern.

Report Approvers:

Approver: Steve Tafuni

Inspection Approval Date: 01/24/2018