

#### **WASTE MANAGEMENT OF NORTH FLORIDA**

Trail Ridge Landfill, Inc. 5110 U.S. Highway 301 South Baldwin, FL 32234-3608 P: 904.289.9100 F: 904.289.9013

March 6, 2019

Brian Durden Florida Department of Environmental Protection 8800 Baymeadows Way, Suite 100 Jacksonville, FL 32256-7590

Re: Trail Ridge Landfill

Methane Monitoring Results/1st Qtr. 2019

FDEP Permit # 0013493-010-SC

I.D. #: NED/16/00033628

Dear Mr. Durden:

In accordance with Specific Condition #37 of the above referenced permit, enclosed please find the 1<sup>st</sup> Quarter 2019 Gas Monitoring Data for Trail Ridge Landfill. As indicated on the report, there was negligible/no detection of methane gas at the site.

If you have any questions or need additional information regarding this submittal, please contact me at (904) 748-6006, or email at eparker1@wm.com.

Respectfully Submitted,

Eric Parker, CHMM

**Environmental Program Manager** 

Florida Market Area

cc: Greg Mathes, Waste Management Craig Pelton, Waste Management Jeff Foster, City of Jacksonville

Transmitted via email to Brian.Durden@dep.state.fl.us

# TRAIL RIDGE LANDFILL QUARTERLY LANDFILL GAS MONITORING AND ACTIVITIES REPORT 1st QUARTER 2019

### SIGNIFICANT ACTIVITIES

(1) Regular gas monitoring occurred on 01/08/2019 and is presented below. No gas was detected.

## **GAS MONITORING RESULTS**

Date Monitored:

January 8, 2019

Analyst:

Walter D. Taylor

Instrument Type:

GEM 5000; Serial No: G504242

Calibration Acceptable:

Yes; Span Gas 15% Volume, Response 15.0%

Water Level Instrument Type: Slope Indicator; Serial No. N/A

Weather Conditions: 63-F, Sunny, Winds: S at 02 Mph

Barometric Pressure: 30.23" Hg

MONITORING POINT	TIME	PRESSURE (INCHES W.C.)	METHANE (% BY VOLUME OF AIR)	METHANE (% LEL)	LIQUID LEVEL (FT TOC)	COMMENTS	
GP-5	08:49	N/A	0.00%	0.00%	0.0'		
GP-6	08:46	N/A	0.00%	0.00%	0.0'		
GP-7	08:41	N/A	0.00%	0.00%	0.01		
GP-8	08:33	N/A	0.00%	0.00%	0.0		
GP-9	08:29	N/A	0,00%	0.00%	0.0'		
GP-10	08:25	N/A	0.00%	0.00%	0.0'		
MM-I	09:13	N/A	0.00%	0.00%	N/A	Scale House South	
MM-2	09:11	N/A	0.00%	0.00%	N/A	Scale House North	
MM-3	09:09	N/A	0.00%	0.00%	N/A	Admin Building	
MM-4	09:03	N/A	0.00%	0.00%	N/A	OP's Building 1st Floor	
MM-5	09:06	N/A	0.00%	0.00%	N/A	OP's Building 2 <sup>nd</sup> Floor	
MM-6	08:56	N/A	0,00%	0.00%	N/A	LES Control Room	
MM-7	08:58	N/A	0.00%	0.00%	N/A	LES Engine Room	
MM-8	09:19	N/A	0.00%	0.00%	N/A	IET Office	
MM-9	09:18	N/A	0.00%	0.00%	N/A	IET Conex	
MM-10	09:18	N/A	0.00%	0.00%	N/A	WM Conex	

Comments: GP-are permanent probes; MM-are in structure locations



January 8, 2019

Eric Parker Waste Management at Trail Ridge Landfill 5110 US Hwy 301 South Baldwin, FL 32234

Subj: Quarterly Monitoring Calibration Report

Dear Mr. Parker,

The following calibration information is provided in reference in support of the Quarterly Landfill Gas Monitoring and Activities Report.

Date of Calibration	08JAN2019		
Calibration Gas:	Span Gas 15% CH4, 15% CO2, Balance N2		
Lot Number:	746519		
Expiration Date:	JUL2020		
Weather Conditions	63-F, Sunny, Winds: S at 2 MPH		
Barometric Pressure	30.23" HG		

#### **GEM 5000 Calibration Details:**

Device Name	Date Time	CH4 (Methane)(%)	CO2 (Carbon Dioxide)(%)	O2 (Oxygen)(%)	Balance Gas(%)
TRLFLDCA	1/8/2019 7:58	14.9	14.9	0.1	70.1
TRLFLDCA	1/8/2019 7:59	0	0	11	89

Respectfully,

Walter D. Taylor

**Landfill Gas Manager** 

Integrated Environmental Technology





