ORLANDO FIRE DEPARTMENT

25228

Occupancy ID: 25228
Location: 548 N MISSION RD
City/State: ORLANDO, FL

Business Name: EMPIRE TIRE
Business Phone: (407)250-5875
Station No: Station 09 **Occupancy:** Industrial

Contact Name		Prty	Mailing Address		Day Time Phone	After Hours Phone
CLIFF McFADDEN	Occupant	1	548 N MISSION RD	ORLANDO, FL 32808	(407)822-0944	(321)303-2096

Activities:	Assigned to:	Assignment Date:	Schedule Date:
INSP-Full Fire Inspection	HURSH, James	01/08/2021	02/08/2021

THIS SURVEY IS PERFORMED BY THE CITY OF ORLANDO FIRE DEPARTMENT IN AN EFFORT TO PREVENT LOSS OF LIFE OR PROPERTY. THIS REPORT ADVISES YOU OF FIRE AND/OR LIFE SAFETY HAZARDS WHICH REQUIRE YOUR IMMEDIATE ATTENTION. EACH OF THE HAZARD(S) INDICATED HEREIN IS IN VIOLATION OF THE ORLANDO FIRE PREVENTION CODE. FOR FURTHER INFORMATION PLEASE CONTACT THE FIRE PREVENTION OFFICE AT 407-246-2386.

Access:
- ○ Address visible
- ○ Fire protection equipment
- ○ FDC connection
- ○ Gate optical detector
- ○ Hydrant access
- ○ Key box (verified)
- ○ Maintain fire lanes

Electrical:
- ○ Circuit identification
- ○ Covers/blanks/junction box missing
- ○ Defective equipment/wiring
- ○ Door labeled
- ○ Improper breakers/fuses/locks
- ○ Improper use/placement of extension cords/overloaded circuit
- ○ Panel accessibility

Exit:
- ○ Door(s) inoperable
- ○ Emergency/Exit sign(s) inoperable
- ○ Exits not adequately enclosed
- ○ Exits not properly arranged
- ○ Improper door swing
- ○ Keep fire doors closed
- ○ Maintain self-closers
- ○ Overcrowding
- ○ Provide approved door assembly
- ○ Provide/maintain rated corridor
- ○ Provide exit sign(s)
- ○ Remove obstruction aisles/exit way
- ○ Remove storage under stairs
- ○ Remove unapproved locks/hardware
- ○ Vertical openings not protected

False Fire Alarm:
- ○ 1 – 2 $0.00
- ○ 3 – 4 $250.00
- ○ 5 - 6 $300.00
- ○ 7 + $350.00

Fire Extinguishers:
- ○ Conspicuously located
- ○ Not accessible

Fire Protection:
- ○ Missing detector(s)
- ○ No sprinkler protection under stairs
- ○ No supervision
- ○ Provide 18" clearance
- ○ Provide spare heads/wrench
- ○ Sprinkler head(s) painted/corroded/ damaged/escutcheon plates missing
- ○ Sprinkler impairment

Flammable Liquids:
- ○ Improper use/storage/dispensing
- ○ Improper container/provide cabinet
- ○ MSDS sheets needed

Heating:
- ○ HVAC inadequate
- ○ Provide/maintain proper clearance around vents/exhaust/water heater

Miscellaneous:
- ○ Clean dryer vents
- ○ Housekeeping issues
- ○ Illegal burning
- ○ Interior finish inadequate
- ○ Provide fuel shut off
- ○ Remove BBQ grill
- ○ Remove rubbish/waste/trash or weeds from building

Permit Issued:
- ○ 18A/Tent
- ○ Fireworks/Pyro/Sp.Effects
- ○ Flam./Comb. Liquids
- ○ Hazardous Material
- ○ Temp. Assembly
- ○ Open Burning

Permit Required:
- ○ Provide permit for work being done

Pre Fire Plan:
- ○ Conducted/Reviewed/Needed

Provide Records for all installed:
- ○ Fire protection equipment

Service/Maintain/Text/Tag:
- ○ Detectors ✓
- ○ Fire Alarm
- ○ Fire Extinguisher JUNE 2020 TAS
- ○ Fire Pump
- ○ Generator
- ○ Hydrant(s)/painted
- ○ Hood System
- ○ Sprinklers
- ○ Standpipe/Hoses

80BC Bottles JAN 2021 TAS ✓

Signage Required
- ○ Fire Lane
- ○ "No Smoking"
- ○ Occupant Load
- ○ Provide 704 Placard
- ○ Stair numbering

Storage:
- ○ Disorderly
- ○ Too high

Other:
- ○ CEB action required
- ○ Referral to Permitting Services
- ○ Unable to Contact

ANNUAL FIRE PREVENTION REVIEW FOR 2021

Remarks: NO MAJOR ISSUES / NOTED TODAY
✗ SATISFACTORY APPROVAL ISSUED.

(Note to Customer: Signature below is to acknowledge receipt of this report)

Heather Garcia / Empire			1/27/21
Customer Name (Print)		**Signature**	**Date**
Jim Hursh	11298	x James [illegible] Hursh	01/27/21 / 11298
Company Officer Name (Print)	**Emp.#**	**Signature**	**Date and Time**
321 436-8854		**Reinspection Date**	

Distribution: Original (WHITE) - Fire Safety Management Division   Copy (YELLOW) - Business Owner