

**From:** oracle@depdbprod.dep.state.fl.us**Sent:** Monday, April 12, 2021 01:50 AM**To:**

tayo.olayiwola@dep.state.fl.us,will.carlquist@floridadep.gov,steven.tafuni@dep.state.fl.us,emily.wargo@dep.state.fl.us,kelby.a.callahan@floridadep.gov,philip.ciaravella@dep.state.fl.us,chad.fetrow@dep.state.fl.us,melissa.madden@floridadep.gov,joseph.dertien@dep.state.fl.us,sarah.neff@floridadep.gov,justin.chamberlain@dep.state.fl.us,kaitlyn.newsome@floridadep.gov,steve.morgan@floridadep.gov,elizabeth.kromhout@dep.state.fl.us,clark.b.moore@dep.state.fl.us,jeremy.r.hart@floridadep.gov,javier.ramirez@dep.state.fl.us,swd\_waste@floridadep.gov,alexis.black@dep.state.fl.us

**Cc:** karen.demirpolat@dep.state.fl.us**Subject:** Production-WACS Electronic Upload for Facility 00044795

Groundwater data has been electronically uploaded to WACS for  
Solid Waste WACS Facility: 00044795-LENA RD COUNTY LF  
District: SWD County: MANATEE

Lab EDD File Name: 44795\_20201116\_SWidd.txt

Field EDD File Name: 44795\_20201116\_SWfdd.txt

Oculus Document Link for ADaPT EDD (single ZIP file):

[https://depdms.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&\[guid=8.324239.1\]&\[profile=Discovery\\_Compliance\]](https://depdms.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&[guid=8.324239.1]&[profile=Discovery_Compliance])

Click on the above link to download a ZIP file of the ADaPT lab EDD, lab EDD error log and field EDDs.

Monitoring Plans and Reports Document Type for a specific WACS Facility ID:

[https://fldeploc.dep.state.fl.us/rcra\\_epa/DocLog/EDD\\_source.asp?SampleDate=20201116&WacsID=44795](https://fldeploc.dep.state.fl.us/rcra_epa/DocLog/EDD_source.asp?SampleDate=20201116&WacsID=44795)

Regulatory Compliance ASP Report:

[https://fldeploc.dep.state.fl.us/www\\_wacs/Reports/SW\\_Facility\\_Testsite\\_Results\\_Analysis\\_Body\\_Only.asp?facilityid=44795&sample\\_year=2020&sample\\_month=11](https://fldeploc.dep.state.fl.us/www_wacs/Reports/SW_Facility_Testsite_Results_Analysis_Body_Only.asp?facilityid=44795&sample_year=2020&sample_month=11)

Groundwater Data Completeness ASP Report:

[https://fldeploc.dep.state.fl.us/rcra\\_epa/SW\\_GW\\_Reports/SW\\_Facility\\_Testsite\\_Results\\_Analysis\\_Complete\\_Results\\_2.asp?facilityid=44795&sample\\_year=2020&sample\\_month=11](https://fldeploc.dep.state.fl.us/rcra_epa/SW_GW_Reports/SW_Facility_Testsite_Results_Analysis_Complete_Results_2.asp?facilityid=44795&sample_year=2020&sample_month=11)

Groundwater Monitoring Data has been uploaded for the following testsites:

Testsite ID: 0000001665	Testsite Status: A	Sample Date: 11/18/2020	Sample Time: 13:10	Report Type: SEMGW
Testsite ID: 0000021595	Testsite Status: A	Sample Date: 11/16/2020	Sample Time: 11:49	Report Type: SEMGW
Testsite ID: 0000021596	Testsite Status: A	Sample Date: 11/16/2020	Sample Time: 12:28	Report Type: SEMGW
Testsite ID: 0000021597	Testsite Status: A	Sample Date: 11/16/2020	Sample Time: 13:26	Report Type: SEMGW
Testsite ID: 0000021598	Testsite Status: A	Sample Date: 11/16/2020	Sample Time: 14:21	Report Type: SEMGW
Testsite ID: 0000021600	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 09:58	Report Type: SEMGW
Testsite ID: 0000021601	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 10:36	Report Type: SEMGW
Testsite ID: 0000021602	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 11:29	Report Type: SEMGW
Testsite ID: 0000021602	Testsite Status: A	Sample Date: 12/24/2020	Sample Time: 09:37	Report Type: RESMP
Testsite ID: 0000021603	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 11:56	Report Type: SEMGW
Testsite ID: 0000021604	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 12:40	Report Type: SEMGW
Testsite ID: 0000021605	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 13:35	Report Type: SEMGW
Testsite ID: 0000021606	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 14:14	Report Type: SEMGW
Testsite ID: 0000021607	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 15:24	Report Type: SEMGW
Testsite ID: 0000021608	Testsite Status: A	Sample Date: 11/18/2020	Sample Time: 08:46	Report Type: SEMGW
Testsite ID: 0000021609	Testsite Status: A	Sample Date: 11/19/2020	Sample Time: 08:30	Report Type: SEMGW
Testsite ID: 0000021610	Testsite Status: A	Sample Date: 11/17/2020	Sample Time: 14:59	Report Type: SEMGW
Testsite ID: 0000027495	Testsite Status: A	Sample Date: 11/19/2020	Sample Time: 09:24	Report Type: SEMGW
Testsite ID: 0000027496	Testsite Status: A	Sample Date: 11/19/2020	Sample Time: 10:09	Report Type: SEMGW
Testsite ID: 0000027497	Testsite Status: A	Sample Date: 11/19/2020	Sample Time: 11:06	Report Type: SEMGW
Testsite ID: 0000027498	Testsite Status: A	Sample Date: 11/19/2020	Sample Time: 12:04	Report Type: SEMGW
Testsite ID: 0000027499	Testsite Status: A	Sample Date: 11/19/2020	Sample Time: 12:46	Report Type: SEMGW
Testsite ID: 0000027500	Testsite Status: A	Sample Date: 11/19/2020	Sample Time: 13:21	Report Type: SEMGW
Testsite ID: 0000027500	Testsite Status: A	Sample Date: 12/24/2020	Sample Time: 10:30	Report Type: RESMP
Testsite ID: 0000027502	Testsite Status: A	Sample Date: 11/16/2020	Sample Time: 09:02	Report Type: SEMGW
Testsite ID: 0000027503	Testsite Status: A	Sample Date: 11/16/2020	Sample Time: 09:57	Report Type: SEMGW
Testsite ID: 0000030026	Testsite Status: A	Sample Date: 11/16/2020	Sample Time: 10:53	Report Type: SEMGW