

From: oracle@depdbprod.dep.state.fl.us
Sent: Monday, July 26, 2021 01:39 AM
To:

tayo.olayiwola@dep.state.fl.us, philip.ciaravella@dep.state.fl.us, chad.fetrow@dep.state.fl.us, joseph.dertien@dep.state.fl.us, elizabeth.kromhout@dep.state.fl.us, clark.b.moore@dep.state.fl.us, jeremy.r.hart@floridadep.gov, frederick.kocher@floridadep.gov, dale.melton@dep.state.fl.us, randall.cunningham@dep.state.fl.us

Cc: karen.demirpolat@dep.state.fl.us

Subject: Production-WACS Electronic Upload for Facility 00087081

Groundwater data has been electronically uploaded to WACS for
Solid Waste WACS Facility: 00087081-VISTA LANDFILL, LLC (BUTTREY/KEENE RD SOUTH)
District: CD County: ORANGE

Lab EDD File Name: 87081_20210607_SWldd.txt

Field EDD File Name: 87081_20210607_swfdd.txt

Oculus Document Link for ADaPT EDD (single ZIP file):

[https://depeds.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&\[guid=8.328689.1\]&\[profile=Discovery_Compliance\]](https://depeds.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&[guid=8.328689.1]&[profile=Discovery_Compliance])

Click on the above link to download a ZIP file of the ADaPT lab EDD, lab EDD error log and field EDDs.

Monitoring Plans and Reports Document Type for a specific WACS Facility ID:

https://fldeploc.dep.state.fl.us/rcra_epa/DocLog/EDD_source.asp?SampleDate=20210607&WacsID=87081

Regulatory Compliance ASP Report:

https://fldeploc.dep.state.fl.us/www_wacs/Reports/SW_Facility_Testsite_Results_Analysis_Body_Only.asp?facilityid=87081&sample_year=2021&sample_month=06

Groundwater Data Completeness ASP Report:

https://fldeploc.dep.state.fl.us/rcra_epa/SW_GW_Reports/SW_Facility_Testsite_Results_Analysis_Complete_Results_2.asp?facilityid=87081&sample_year=2021&sample_month=06

Groundwater Monitoring Data has been uploaded for the following testsites:

Testsite ID: 0000019335	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 13:21	Report Type: SEMGW
Testsite ID: 0000019337	Testsite Status: A	Sample Date: 06/08/2021	Sample Time: 08:10	Report Type: SEMGW
Testsite ID: 0000019339	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 10:14	Report Type: SEMGW
Testsite ID: 0000019341	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 10:52	Report Type: SEMGW
Testsite ID: 0000019343	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 11:37	Report Type: SEMGW
Testsite ID: 0000019345	Testsite Status: A	Sample Date: 06/08/2021	Sample Time: 09:12	Report Type: SEMGW
Testsite ID: 0000019347	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 12:25	Report Type: SEMGW
Testsite ID: 0000019868	Testsite Status: A	Sample Date: 06/08/2021	Sample Time: 07:20	Report Type: SEMGW
Testsite ID: 0000019869	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 09:06	Report Type: SEMGW
Testsite ID: 0000019873	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 08:32	Report Type: SEMGW
Testsite ID: 0000021926	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 09:40	Report Type: SEMGW
Testsite ID: 0000021928	Testsite Status: A	Sample Date: 06/07/2021	Sample Time: 07:59	Report Type: SEMGW