

From: oracle@depdbprod.dep.state.fl.us
Sent: Friday, October 29, 2021 01:53 AM
To:

tayo.olayiwola@dep.state.fl.us, jeffrey.schroer@dep.state.fl.us, emerson.raulerson@dep.state.fl.us, neil.hornick@dep.state.fl.us, philip.ciaravella@dep.state.fl.us, chad.fetrow@dep.state.fl.us, julia.boesch@dep.state.fl.us, joseph.dertien@dep.state.fl.us, elizabeth.kromhout@dep.state.fl.us, clark.b.moore@dep.state.fl.us, michael.bogin@dep.state.fl.us, jeremy.r.hart@floridadep.gov, frederick.kocher@floridadep.gov, brian.durden@dep.state.fl.us
Cc: ram.sankuratri@floridadep.gov
Subject: Production-WACS Electronic Upload for Facility 00033628

Groundwater data has been electronically uploaded to WACS for
 Solid Waste WACS Facility: 00033628-TRAIL RIDGE LANDFILL, INC.
 District: NED County: DUVAL

Lab EDD File Name: 33628_20210810_SWldd.txt
 Field EDD File Name: 33628_20210810_SWfdd.txt

Oculus Document Link for ADaPT EDD (single ZIP file):

[https://fdeplc.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&\[guid=8.331280.1\]&\[profile=Discovery_Compliance\]](https://fdeplc.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&[guid=8.331280.1]&[profile=Discovery_Compliance])

Click on the above link to download a ZIP file of the ADaPT lab EDD, lab EDD error log and field EDDs.

Monitoring Plans and Reports Document Type for a specific WACS Facility ID:
https://fdeplc.dep.state.fl.us/rcra_epa/DocLog/EDD_source.asp?SampleDate=20210810&WacsID=33628

Regulatory Compliance ASP Report:
https://fdeplc.dep.state.fl.us/www_wacs/Reports/SW_Facility_Testsite_Results_Analysis_Body_Only.asp?facilityid=33628&sample_year=2021&sample_month=08

Groundwater Data Completeness ASP Report:
https://fdeplc.dep.state.fl.us/rcra_epa/SW_GW_Reports/SW_Facility_Testsite_Results_Analysis_Complete_Results_2.asp?facilityid=33628&sample_year=2021&sample_month=08

Groundwater Monitoring Data has been uploaded for the following testsites:

Testsite ID: 0000017180	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 12:21	Report Type: SEMGW
Testsite ID: 0000017181	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 12:51	Report Type: SEMGW
Testsite ID: 0000017182	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 13:57	Report Type: SEMGW
Testsite ID: 0000017183	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 12:51	Report Type: SEMGW
Testsite ID: 0000017187	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 07:05	Report Type: SEMGW
Testsite ID: 0000017188	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 07:33	Report Type: SEMGW
Testsite ID: 0000017190	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 07:50	Report Type: SEMGW
Testsite ID: 0000017191	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 08:21	Report Type: SEMGW
Testsite ID: 0000017199	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 08:02	Report Type: SEMGW
Testsite ID: 0000017200	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 08:32	Report Type: SEMGW
Testsite ID: 0000017201	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 08:51	Report Type: SEMGW
Testsite ID: 0000017206	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 10:23	Report Type: SEMGW
Testsite ID: 0000017207	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 10:52	Report Type: SEMGW
Testsite ID: 0000017209	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 11:30	Report Type: SEMGW
Testsite ID: 0000017211	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 11:00	Report Type: SEMGW
Testsite ID: 0000017357	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 09:51	Report Type: SEMGW
Testsite ID: 0000017358	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 09:21	Report Type: SEMGW
Testsite ID: 0000020104	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 11:51	Report Type: SEMGW
Testsite ID: 0000020105	Testsite Status: A	Sample Date: 08/10/2021	Sample Time: 11:21	Report Type: SEMGW
Testsite ID: 0000020107	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 10:04	Report Type: SEMGW
Testsite ID: 0000020108	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 09:33	Report Type: SEMGW
Testsite ID: 0000020109	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 09:02	Report Type: SEMGW
Testsite ID: 0000020844	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 11:03	Report Type: SEMGW
Testsite ID: 0000020845	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 10:34	Report Type: SEMGW
Testsite ID: 0000030227	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 13:45	Report Type: SEMGW
Testsite ID: 0000030228	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 13:16	Report Type: SEMGW
Testsite ID: 0000030229	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 12:06	Report Type: SEMGW
Testsite ID: 0000030230	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 11:36	Report Type: SEMGW
Testsite ID: 0000030231	Testsite Status: A	Sample Date: 08/11/2021	Sample Time: 12:39	Report Type: SEMGW
Testsite ID: 0000030233	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 08:19	Report Type: SEMGW

Testsite ID: 0000030368	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 10:30	Report Type: SEMGW
Testsite ID: 0000030426	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 09:45	Report Type: SEMGW
Testsite ID: 0000030427	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 08:50	Report Type: SEMGW
Testsite ID: 0000030428	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 08:30	Report Type: SEMGW
Testsite ID: 0000030429	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 09:15	Report Type: SEMGW
Testsite ID: 0000030430	Testsite Status: A	Sample Date: 08/12/2021	Sample Time: 07:48	Report Type: SEMGW