

**From:** oracle@depdbprod.dep.state.fl.us  
**Sent:** Monday, January 31, 2022 01:52 AM  
**To:** tayo.olayiwola@dep.state.fl.us, steven.tafuni@dep.state.fl.us, emily.wargo@dep.state.fl.us, kelby.a.callahan@floridadep.gov, philip.ciaravella@dep.state.fl.us, chad.fetrow@dep.state.fl.us, melissa.madden@floridadep.gov, joseph.dertien@dep.state.fl.us, justin.chamberlain@dep.state.fl.us, steve.morgan@floridadep.gov, lukas.medo@floridadep.gov, ryan.d.mcmillan@floridadep.gov, elizabeth.kromhout@dep.state.fl.us, clark.b.moore@dep.state.fl.us, jeremy.r.hart@floridadep.gov, javier.ramirez@dep.state.fl.us, frederick.kocher@floridadep.gov, swd\_waste@floridadep.gov, abigail.mcaleer@floridadep.gov  
**Cc:** ram.sankuratri@floridadep.gov  
**Subject:** Production-WACS Electronic Upload for Facility 00045799

Groundwater data has been electronically uploaded to WACS for  
Solid Waste WACS Facility: 00045799-PASCO COUNTY RESOURCE RECOVERY  
District: SWD County: PASCO

Lab EDD File Name: 45799\_20211109\_SWlidd.txt  
Field EDD File Name: 45799\_20211109\_SWfidd.txt  
Oculus Document Link for ADaPT EDD (single ZIP file):  
[https://fdepdms.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&\[guid=8.335367.1\]&\[profile=Discovery\\_Compliance\]](https://fdepdms.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&[guid=8.335367.1]&[profile=Discovery_Compliance])

Click on the above link to download a ZIP file of the ADaPT lab EDD, lab EDD error log and field EDDs.

Monitoring Plans and Reports Document Type for a specific WACS Facility ID:  
[https://fldeploc.dep.state.fl.us/rcra\\_epa/DocLog/EDD\\_source.asp?SampleDate=20211109&WacsID=45799](https://fldeploc.dep.state.fl.us/rcra_epa/DocLog/EDD_source.asp?SampleDate=20211109&WacsID=45799)

Regulatory Compliance ASP Report:  
[https://fldeploc.dep.state.fl.us/www\\_wacs/Reports/SW\\_Facility\\_Testsite\\_Results\\_Analysis\\_Body\\_Only.asp?facilityid=45799&sample\\_year=2021&sample\\_month=11](https://fldeploc.dep.state.fl.us/www_wacs/Reports/SW_Facility_Testsite_Results_Analysis_Body_Only.asp?facilityid=45799&sample_year=2021&sample_month=11)

Groundwater Data Completeness ASP Report:  
[https://fldeploc.dep.state.fl.us/rcra\\_epa/SW\\_GW\\_Reports/SW\\_Facility\\_Testsite\\_Results\\_Analysis\\_Complete\\_Results\\_2.asp?facilityid=45799&sample\\_year=2021&sample\\_month=11](https://fldeploc.dep.state.fl.us/rcra_epa/SW_GW_Reports/SW_Facility_Testsite_Results_Analysis_Complete_Results_2.asp?facilityid=45799&sample_year=2021&sample_month=11)

Groundwater Monitoring Data has been uploaded for the following testsites:

Testsite ID: 0000002340	Testsite Status: A	Sample Date: 11/19/2021	Sample Time: 12:59	Report Type: SEMGW
Testsite ID: 0000002341	Testsite Status: A	Sample Date: 11/19/2021	Sample Time: 12:56	Report Type: SEMGW
Testsite ID: 0000002342	Testsite Status: A	Sample Date: 11/19/2021	Sample Time: 10:33	Report Type: SEMGW
Testsite ID: 0000002382	Testsite Status: A	Sample Date: 11/09/2021	Sample Time: 08:09	Report Type: SEMGW
Testsite ID: 0000002386	Testsite Status: A	Sample Date: 12/16/2021	Sample Time: 14:47	Report Type: SEMGW
Testsite ID: 0000002387	Testsite Status: A	Sample Date: 11/09/2021	Sample Time: 11:40	Report Type: SEMGW
Testsite ID: 0000002388	Testsite Status: A	Sample Date: 11/15/2021	Sample Time: 09:50	Report Type: SEMGW
Testsite ID: 0000002389	Testsite Status: A	Sample Date: 11/10/2021	Sample Time: 13:00	Report Type: SEMGW
Testsite ID: 0000002390	Testsite Status: A	Sample Date: 11/22/2021	Sample Time: 12:32	Report Type: SEMGW
Testsite ID: 0000002510	Testsite Status: A	Sample Date: 11/30/2021	Sample Time: 08:15	Report Type: SEMGW
Testsite ID: 0000002511	Testsite Status: A	Sample Date: 11/30/2021	Sample Time: 10:52	Report Type: SEMGW
Testsite ID: 0000002512	Testsite Status: A	Sample Date: 11/30/2021	Sample Time: 09:28	Report Type: SEMGW
Testsite ID: 0000019670	Testsite Status: A	Sample Date: 11/09/2021	Sample Time: 13:55	Report Type: SEMGW
Testsite ID: 0000019758	Testsite Status: A	Sample Date: 11/10/2021	Sample Time: 13:54	Report Type: SEMGW
Testsite ID: 0000019759	Testsite Status: A	Sample Date: 11/15/2021	Sample Time: 10:41	Report Type: SEMGW
Testsite ID: 0000019764	Testsite Status: A	Sample Date: 11/15/2021	Sample Time: 14:30	Report Type: SEMGW
Testsite ID: 0000019766	Testsite Status: A	Sample Date: 11/30/2021	Sample Time: 13:52	Report Type: SEMGW
Testsite ID: 0000023065	Testsite Status: A	Sample Date: 11/29/2021	Sample Time: 13:32	Report Type: SEMGW
Testsite ID: 0000023066	Testsite Status: A	Sample Date: 11/29/2021	Sample Time: 14:30	Report Type: SEMGW
Testsite ID: 0000023067	Testsite Status: A	Sample Date: 12/02/2021	Sample Time: 13:24	Report Type: SEMGW
Testsite ID: 0000023444	Testsite Status: A	Sample Date: 12/02/2021	Sample Time: 08:36	Report Type: SEMGW
Testsite ID: 0000023446	Testsite Status: A	Sample Date: 12/02/2021	Sample Time: 09:23	Report Type: SEMGW
Testsite ID: 0000023448	Testsite Status: A	Sample Date: 12/02/2021	Sample Time: 10:57	Report Type: SEMGW
Testsite ID: 0000023450	Testsite Status: A	Sample Date: 11/23/2021	Sample Time: 12:57	Report Type: SEMGW
Testsite ID: 0000023451	Testsite Status: A	Sample Date: 11/23/2021	Sample Time: 12:07	Report Type: SEMGW
Testsite ID: 0000023452	Testsite Status: A	Sample Date: 12/01/2021	Sample Time: 16:32	Report Type: SEMGW