

From: oracle@depdbprod.dep.state.fl.us
Sent: Monday, February 28, 2022 02:11 AM
To: tayo.olayiwola@dep.state.fl.us,ryan.snyder@dep.state.fl.us,narrisa.pannell@dep.state.fl.us,philip.c.iaravella@dep.state.fl.us,chad.fetrow@dep.state.fl.us,joseph.dertien@dep.state.fl.us,gus.rios@dep.state.fl.us,elizabeth.kromhout@dep.state.fl.us,clark.b.moore@dep.state.fl.us,jeremy.r.hart@floridade.p.gov,frederick.kocher@floridadep.gov,renee.kwiat@dep.state.fl.us,southdistrict.sws@dep.state.fl.us
Cc: ram.sankuratri@floridadep.gov
Subject: Production-WACS Electronic Upload for Facility 00093715

Groundwater data has been electronically uploaded to WACS for
Solid Waste WACS Facility: 00093715-LEE COUNTY RESOURCE RECOVERY FACILITY
District: SD County: LEE

Lab EDD File Name: 93715_20210818_2_SWidd.txt
Field EDD File Name: 93715_20210818_2_SWfdd.txt
Oculus Document Link for ADaPT EDD (single ZIP file):
[https://depedms.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&\[guid=8.337489.1\]&\[profile=Discovery_Compliance\]](https://depedms.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&[guid=8.337489.1]&[profile=Discovery_Compliance])

Click on the above link to download a ZIP file of the ADaPT lab EDD, lab EDD error log and field EDDs.

Monitoring Plans and Reports Document Type for a specific WACS Facility ID:
https://fldeploc.dep.state.fl.us/rcra_epa/DocLog/EDD_source.asp?SampleDate=20210818&WacsID=93715

Regulatory Compliance ASP Report:
https://fldeploc.dep.state.fl.us/www_wacs/Reports/SW_Facility_Testsite_Results_Analysis_Body_Only.asp?facilityid=93715&sample_year=2021&sample_month=08

Groundwater Data Completeness ASP Report:
https://fldeploc.dep.state.fl.us/rcra_epa/SW_GW_Reports/SW_Facility_Testsite_Results_Analysis_Complete_Results_2.asp?facilityid=93715&sample_year=2021&sample_month=08

Groundwater Monitoring Data has been uploaded for the following testsites:

Testsite ID: 0000023402	Testsite Status: A	Sample Date: 11/02/2021	Sample Time: 09:01	Report Type: SEMGW
Testsite ID: 0000023404	Testsite Status: A	Sample Date: 08/18/2021	Sample Time: 11:53	Report Type: SEMGW
Testsite ID: 0000023409	Testsite Status: A	Sample Date: 08/18/2021	Sample Time: 12:51	Report Type: SEMGW
Testsite ID: 0000023411	Testsite Status: A	Sample Date: 08/18/2021	Sample Time: 14:57	Report Type: SEMGW
Testsite ID: 0000023413	Testsite Status: A	Sample Date: 08/18/2021	Sample Time: 14:08	Report Type: SEMGW
Testsite ID: 0000027415	Testsite Status: A	Sample Date: 08/18/2021	Sample Time: 16:10	Report Type: SEMGW