

From: oracle@depdbprod.dep.state.fl.us
Sent: Tuesday, August 02, 2022 01:54 AM
To:

tayo.olayiwola@dep.state.fl.us, philip.ciaravella@dep.state.fl.us, chad.fetrow@dep.state.fl.us, joseph.dertien@dep.state.fl.us, elizabeth.kromhout@dep.state.fl.us, clark.b.moore@dep.state.fl.us, jeremy.r.hart@floridadep.gov, frederick.kocher@floridadep.gov, dale.melton@dep.state.fl.us, randall.cunningham@dep.state.fl.us

Cc: ram.sankuratri@floridadep.gov

Subject: Production-WACS Electronic Upload for Facility 00021012

Groundwater data has been electronically uploaded to WACS for
Solid Waste WACS Facility: 00021012-FRIENDS RECYCLING FORMERLY OCALA RECYCLING
District: CD County: MARION

Lab EDD File Name: 21012_20220706_SWl1dd.txt

Field EDD File Name: 21012_20220706_SWf1dd.txt

Oculus Document Link for ADaPT EDD (single ZIP file):

[https://depedsms.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&\[guid=8.345807.1\]&\[profile=Discovery_Compliance\]](https://depedsms.dep.state.fl.us/Oculus/servlet/shell?command=getEntity&[guid=8.345807.1]&[profile=Discovery_Compliance])

Click on the above link to download a ZIP file of the ADaPT lab EDD, lab EDD error log and field EDDs.

Monitoring Plans and Reports Document Type for a specific WACS Facility ID:

https://fldeploc.dep.state.fl.us/rcra_epa/DocLog/EDD_source.asp?SampleDate=20220706&WacsID=21012

Regulatory Compliance ASP Report:

https://fldeploc.dep.state.fl.us/www_wacs/Reports/SW_Facility_Testsite_Results_Analysis_Body_Only.asp?facilityid=21012&sample_year=2022&sample_month=07

Groundwater Data Completeness ASP Report:

https://fldeploc.dep.state.fl.us/rcra_epa/SW_GW_Reports/SW_Facility_Testsite_Results_Analysis_Complete_Results_2.asp?facilityid=21012&sample_year=2022&sample_month=07

Groundwater Monitoring Data has been uploaded for the following testsites:

Testsite ID: 0000018811	Testsite Status: A	Sample Date: 07/06/2022	Sample Time: 08:23	Report Type: SEMCD
Testsite ID: 0000022912	Testsite Status: A	Sample Date: 07/06/2022	Sample Time: 10:15	Report Type: SEMCD
Testsite ID: 0000022913	Testsite Status: A	Sample Date: 07/06/2022	Sample Time: 09:47	Report Type: SEMCD
Testsite ID: 0000022914	Testsite Status: A	Sample Date: 07/06/2022	Sample Time: 10:40	Report Type: SEMCD
Testsite ID: 0000022915	Testsite Status: A	Sample Date: 07/06/2022	Sample Time: 09:14	Report Type: SEMCD
Testsite ID: 0000022916	Testsite Status: A	Sample Date: 07/06/2022	Sample Time: 08:52	Report Type: SEMCD