

Trail Ridge Landfill

Human Review Statement:

This is an automated data review produced by the FDEP Validator software. This report does not supercede FDEP rules or standards and may not contain all violations of FDEP rules and standards. This report should be reviewed by a qualified staff member.

Sample ID: 660-24485-11	Matrix: W	Well Type: CO - Compliance
Monitoring Site: MWB12I		Sample Date: August 5, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter N	lame I	Rslt Qual	Units		
Acenaphthene	9	0.48 JU	ug/L	QA/QC Qualifier J	
	Accuracy limits exceeded or Precision limits ex			Qual meaning: Estimated value; value not accurat	le.
Chrysene		0.066 JU	ug/L	QA/QC Qualifier J	
Comment: Fluorene		0.48 JU	ug/L	Qual meaning: Estimated value; value not accurat QA/QC Qualifier J	e.
Comment: Naphthalene		0.24 JU	ug/L	Qual meaning: Estimated value; value not accurat QA/QC Qualifier J	ie.
Comment: Pyrene		0.085 JU	ug/L	Qual meaning: Estimated value; value not accurate QA/QC Qualifier J	e.
Comment:				Qual meaning: Estimated value; value not accurate	ie.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 1 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24485-12	Matrix: W	Well Type: DE - Detection
Monitoring Site: MWB34I		Sample Date: August 5, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter N	ame R	slt Qual	Units		
Acenaphthene		0.48 JU	ug/L	QA/QC Qualifier	J
Comment:	Accuracy limits exceeded or Precision limits exce	eeded		Qual meaning:	Estimated value; value not accurate.
Ammonia		0.087 J	mg/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Chrysene		0.066 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Fluorene		0.48 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Naphthalene		0.24 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Pyrene		0.085 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 2 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24485-13	Matrix: W	Well Type: BG - Background
Monitoring Site: MWB2I		Sample Date: August 5, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Na	me Rslt	Qual	Units		
Acenaphthene	0.	.48 JU	ug/L	QA/QC Qualifier	J
Comment: A	ccuracy limits exceeded or Precision limits exceed	ed		Qual meaning:	Estimated value; value not accurate.
Chrysene	0.0	066 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Fluorene	0.	.48 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Naphthalene	0.	.24 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Pyrene	0.0)85 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 3 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-2	4485-14	Matrix: W	Well Type: OT - Other
Monitoring Site:	Not Blank-DUP1		Sample Date: August 5, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual	Units	
Acenaphthene	0.48 JU	ug/L	QA/QC Qualifier J
Comment: Accura	acy limits exceeded or Precision limits exceeded		Qual meaning: Estimated value; value not accurate.
Chrysene	0.066 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Fluorene	0.48 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Naphthalene	0.24 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Pyrene	0.085 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 4 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24485-15	Matrix: W	Well Type: DE - Detection
Monitoring Site: MWB34D		Sample Date: August 5, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Na	ame Rslt Qua	al	Units	
Acenaphthene	0.48 Jl	U	ug/L	QA/QC Qualifier J
Comment:	Accuracy limits exceeded or Precision limits exceeded			Qual meaning: Estimated value; value not accurate.
Chrysene	0.066 JI	U	ug/L	QA/QC Qualifier J
Comment:				Qual meaning: Estimated value; value not accurate.
Fluorene	0.48 Jl	U	ug/L	QA/QC Qualifier J
Comment:				Qual meaning: Estimated value; value not accurate.
Naphthalene	0.24 Jl	U	ug/L	QA/QC Qualifier J
Comment:				Qual meaning: Estimated value; value not accurate.
Pyrene	0.085 JI	U	ug/L	QA/QC Qualifier J
Comment:				Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 5 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24485-16	Matrix: W	Well Type: CO - Compliance
Monitoring Site: MWB12S		Sample Date: August 5, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual	l Un	nits		
Acenaphthene	0.48 JU	Ju	ug/L	QA/QC Qualifier	J
Comment: Accu	racy limits exceeded or Precision limits exceeded			Qual meaning:	Estimated value; value not accurate.
Chrysene	0.066 JU	Ju	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Fluorene	0.48 JU	Ju	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Naphthalene	0.24 JU	Ju	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Pyrene	0.086 JU	Ju	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 6 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24	4485-7	Matrix: W	Well Type: CO - Compliance
Monitoring Site:	MWB29D		Sample Date: August 5, 2008
Evaluation Type:	QA/QC qualifier h	as been applied	
	Review qualifier	meaning and assess imp	pact on qualified data
Parameter Name		Rslt Qual Units	
Chlorobenzene		0.63 JU ug/L	QA/QC Qualifier J
	. Parties and a data Data is in	a Bartha and a datab	

Comment: Accuracy limits exceeded or Precision limits exceeded

Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 7 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24506-1	Matrix: W	Well Type: DE - Detection
Monitoring Site: MWB33S		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual	Units		
Acenaphthene	0.48 JU	ug/L	QA/QC Qualifier	J
Comment: Accuracy limits exceeded of	or Precision limits exceeded		Qual meaning:	Estimated value; value not accurate.
Bis(2-ethylhexyl) phthalate	1.3 IV	ug/L	QA/QC Qualifier	V
Comment:			Qual meaning:	Analyte was detected in both the sample and the associated method blank.
Chrysene	0.066 JU	ug/L	QA/QC Qualifier	J
Comment: Accuracy limits exceeded of	or Precision limits exceeded		Qual meaning:	Estimated value; value not accurate.
Fluorene	0.48 JU	ug/L	QA/QC Qualifier	J
Comment:			Qual meaning:	Estimated value; value not accurate.
Naphthalene	0.24 JU	ug/L	QA/QC Qualifier	J
Comment:			Qual meaning:	Estimated value; value not accurate.
Pyrene	0.085 JU	ug/L	QA/QC Qualifier	J
Comment:			Qual meaning:	Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24	4506-10	Matrix: W	Well Type:	CO - Com	bliance
Monitoring Site:	MWB7D		Sample Date	e: Augus	t 6, 2008
Evaluation Type:	QA/QC qualifier has b	een applied			
	Review qualifier mea	ning and assess impact or	n qualified data	a	
Parameter Name		Rslt Qual Units			
2,4-D		0.059 JU ug/L	Q	A/QC Qualifier	J
Comment: Accuracy	y limits exceeded or Precision limit	ts exceeded		Qual meaning:	Estimated value; value not accurate.

Versions Report: 3.0.0 Database: 3.7.51 6/24/2005 12:00 Monday, November 24, 2008 Page 9 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24506-11	Matrix: W	Well Type: DE - Detection
Monitoring Site: MWB32I		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual	Units		
2,4-D	0.059 JU	ug/L	QA/QC Qualifier	J
Comment: Accuracy limits exceeded or Precision lin	nits exceeded		Qual meaning:	Estimated value; value not accurate.
Bis(2-ethylhexyl) phthalate	12 V	ug/L	QA/QC Qualifier	V
Comment:			Qual meaning:	Analyte was detected in both the sample and the associated method blank.
Bis(2-ethylhexyl) phthalate	1.3 QU	ug/L	QA/QC Qualifier	Q
Comment:			Qual meaning:	Sample held beyond the accepted holding time

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 10 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-2	4506-12	Matrix: W	Well Type:		
Monitoring Site:	Field Blank		Sample Date:	August 6, 2008	
Evaluation Type: QA/QC qualifier has been applied					
	Review quali	fier meaning and assess impac	t on qualified data		
Parameter Name		Rslt Qual Units			
2,4-D		0.059 JU ug/L	QA/QC	Qualifier J	
Comment: Accurac	y limits exceeded or Pre	cision limits exceeded	Qual	meaning: Estimated value; v	value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 11 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-245	06-2	Matrix: W	Well Type: O	T - Other
Monitoring Site:	Not Blank-DUP3		Sample Date:	August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual	Units	
Acenaphthene	0.48 JU	ug/L	QA/QC Qualifier J
Comment: Accuracy I	imits exceeded or Precision limits exceeded		Qual meaning: Estimated value; value not accurate.
Chrysene	0.066 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Fluorene	0.48 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Naphthalene	0.24 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Pyrene	0.086 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 12 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24506-3	Matrix: W	Well Type: CO - Compliance
Monitoring Site: MWB21S		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual	Units	
Acenaphthene	0.48 JU	ug/L	QA/QC Qualifier J
Comment: Accura	acy limits exceeded or Precision limits exceeded		Qual meaning: Estimated value; value not accurate.
Chrysene	0.066 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Fluorene	0.48 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Naphthalene	0.24 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Pyrene	0.085 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 13 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24506-4	Matrix: W	Well Type: CO - Compliance
Monitoring Site: MWB11S		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Na	me Rslt	Qual	Units		
Acenaphthene	0.	.48 JU	ug/L	QA/QC Qualifier	J
Comment: A	ccuracy limits exceeded or Precision limits exceed	ed		Qual meaning:	Estimated value; value not accurate.
Chrysene	0.0	066 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Fluorene	0.	.48 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Naphthalene	0.	.24 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.
Pyrene	0.0)85 JU	ug/L	QA/QC Qualifier	J
Comment:				Qual meaning:	Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 14 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24506-5	Matrix: W	Well Type: CO - Compliance
Monitoring Site: MWB20S		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter N	lame Rslt Qua	al	Units		
Acenaphthene	e 0.48 J	U	ug/L	QA/QC Qualifier J	
Comment:	Accuracy limits exceeded or Precision limits exceeded			Qual meaning: Estimated value; value not accur	rate.
Chrysene	0.066 J	U	ug/L	QA/QC Qualifier J	
Comment:				Qual meaning: Estimated value; value not accur	rate.
Fluorene	0.48 J	U	ug/L	QA/QC Qualifier J	
Comment:				Qual meaning: Estimated value; value not accur	rate.
Naphthalene	0.24 J	U	ug/L	QA/QC Qualifier J	
Comment:				Qual meaning: Estimated value; value not accu	rate.
Pyrene	0.085 J	U	ug/L	QA/QC Qualifier J	
Comment:				Qual meaning: Estimated value; value not accur	rate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 15 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24506-6	Matrix: W	Well Type: DE - Detection
Monitoring Site: MWB32S		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual	Units	
Acenaphthene	0.48 JU	ug/L	QA/QC Qualifier J
Comment: Accura	acy limits exceeded or Precision limits exceeded		Qual meaning: Estimated value; value not accurate.
Chrysene	0.066 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Fluorene	0.48 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Naphthalene	0.24 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.
Pyrene	0.085 JU	ug/L	QA/QC Qualifier J
Comment:			Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 16 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24506-7	Matrix: W	Well Type: DE - Detection
Monitoring Site: MWB32D		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual	Units		
1,2,4,5-Tetrachlorobenzene	1.1 QU	ug/L	QA/QC Qualifier	Q
Comment: 1,2,4-Trichlorobenzene	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: 1,2-Dichlorobenzene	1.1 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: 1,3-Dichlorobenzene	1.1 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: 1,4-Dichlorobenzene	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: 1,4-Naphthoquinone	1.1 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: 2-Nitrophenol	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: 2-Toluidine	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: 3-Nitroaniline	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: Bis(2-ethylhexyl) phthalate	1.6 IV	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time V
Comment:			Qual meaning:	Analyte was detected in both the sample and the
Butyl benzyl phthalate	1.2 QU	ug/L	QA/QC Qualifier	associated method blank. Q
Comment: Hexachlorocyclopentadiene	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: Methapyrilene	1.1 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: Methyl methanesulfonate	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: N-Nitrosopyrrolidine	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment: Safrole, Total	1.2 QU	ug/L	Qual meaning: QA/QC Qualifier	Sample held beyond the accepted holding time Q
Comment:			Qual meaning:	Sample held beyond the accepted holding time

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 17 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24	506-8	Matrix: W	Well Type: CO - Compliance	
Monitoring Site:	MWB7S		Sample Date: August 6, 2008	
Evaluation Type:	QA/QC qualifier	has been applied		
	Review qualifie	er meaning and assess impact	t on qualified data	
Parameter Name		Rslt Qual Units		
Bis(2-ethylhexyl) phthal	ate	1.6 IV ug/L	QA/QC Qualifier V	
Comment:			Qual meaning: Analyte was detected in both the sample and the associated method blank.	•

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 18 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-2	4506-9	Matrix: W	Well Type: CO - Compliance
Monitoring Site:	MWB7I		Sample Date: August 6, 2008
Evaluation Type:	QA/QC qualifie	er has been applied	
	Review qualif	ier meaning and assess impa	ct on qualified data
Parameter Name		Rslt Qual Units	
2,4-D		0.059 JU ug/L	QA/QC Qualifier J
A course	v limite eveneded or Dre	nician limita avaaadad	Quel magning. Estimated values value not accurate

Comment: Accuracy limits exceeded or Precision limits exceeded

Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 19 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24	1508-1	Matrix: W	Well Type:	OT - Other	
Monitoring Site:	LCS		Sample Date:	August	6, 2008
Evaluation Type:	QA/QC qualifier has be	en applied			
	Review qualifier mean	ing and assess impact on	qualified data		
Parameter Name		Rslt Qual Units			
2,4-D		0.059 JU ug/L	QA	/QC Qualifier	J
Comment: Accuracy	limits exceeded or Precision limits	exceeded	Q	ual meaning:	Estimated value; value not accurate.

Versions Report: 3.0.0 Database: 3.7.51 6/24/2005 12:00 Monday, November 24, 2008 Page 20 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-2	4508-2	Matrix: W	Well Type: S	O - Source
Monitoring Site:	LDSS		Sample Date:	August 6, 2008
Evaluation Type:	QA/QC qualifier has	been applied		
	Review qualifier m	eaning and assess impa	ct on qualified data	
Parameter Name		Rslt Qual Units		
2,4-D		0.06 JU ug/L	QA/C	QC Qualifier J
A course	v limite eveneded or Dresision I	imite eveneded	0.0	al magning. Estimated value value not accurate

Comment: Accuracy limits exceeded or Precision limits exceeded

Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 21 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24509-1	Matrix: W	Well Type: OT - Other
Monitoring Site: SW-1		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual Units	
1,1-Dichloroethene	0.45 JU ug/L	QA/QC Qualifier J
Comment: Accuracy limits exceeded or Preci	ision limits exceeded	Qual meaning: Estimated value; value not accurate.
Benzene	0.5 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Chlorobenzene	0.63 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Toluene	0.53 IJ ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Trichloroethene	0.5 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 22 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24509-2	Matrix: W	Well Type: OT - Other
Monitoring Site: SW-2		Sample Date: August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual Units	
1,1-Dichloroethene	0.45 JU ug/L	QA/QC Qualifier J
Comment: Accuracy limits exceeded or Precision lir	nits exceeded	Qual meaning: Estimated value; value not accurate.
Benzene	0.5 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Chlorobenzene	0.63 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Toluene	0.51 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Trichloroethene	0.5 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 23 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-24509-3	Matrix: W	Well Type:	
Monitoring Site: Trip Blank		Sample Date:	August 6, 2008

Evaluation Type: QA/QC qualifier has been applied

Review qualifier meaning and assess impact on qualified data

Parameter Name	Rslt Qual Units	
1,1-Dichloroethene	0.45 JU ug/L	QA/QC Qualifier J
Comment: Accuracy limits exceeded or Precision limit	ts exceeded	Qual meaning: Estimated value; value not accurate.
Benzene	0.5 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Chlorobenzene	0.63 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Toluene	0.51 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.
Trichloroethene	0.5 JU ug/L	QA/QC Qualifier J
Comment:		Qual meaning: Estimated value; value not accurate.

Versions				
Report:	3.0.0			
Database:	3.7.51	6/24/2005	12:00	

Monday, November 24, 2008 Page 24 of 25 H:\72.tmp

Trail Ridge Landfill

This is an automated data review. Please see the Human Review Statement on page 1 of this report.

Sample ID: 660-2	4510-1	Matrix: W		Well Type: OT - Other	
Monitoring Site:	Cond			Sample Date: August 6, 2008	
Evaluation Type:	QA/QC qualifier has b	een applied			
	Review qualifier mea	ning and asse	ss impact o	on qualified data	
Parameter Name		Rslt Qual	Units		
Heptachlor		0.36 JU	ug/L	QA/QC Qualifier J	
Comment: Accurac	cy limits exceeded or Precision limit	ts exceeded		Qual meaning: Estimated value; value not accurate.	
Pyridine		8.6 JU	ug/L	QA/QC Qualifier J	
Comment:				Qual meaning: Estimated value; value not accurate.	

Versions Report: 3.0.0 Database: 3.7.51 6/24/2005 12:00 Monday, November 24, 2008 Page 25 of 25 H:\72.tmp